

Tech Note for Liquid Filled Pressure Gauges

1. A common step that is overlooked before these are used is cutting the weep plug after installation to allow the needle to zero out. There is a label on the unit to instruct user as such (see image below).



2. Another thing to check is that the gauge is upright, not lying flat (see image below).

