WESTWARD Lever Action Bucket Pump

For Repair Parts, call 1-800-323-0620 24 hours a day – 365 days a year




Figure 2 – Repair Parts Illustration for Model 5NUD5

Repair Parts List

Reference Number	Description	Part Number	Qty.
1	Hose Assembly	TTSAHOS48BLPG	1

Manufactured for Grainger International, Inc. 100 Grainger Pkwy., Lake Forest IL 60045 U.S.A.

